

Remit To: **Jack Doheny Company** PO BOX 675<u>546</u> DETROIT, MI 48267-5546

INVOICE

Invoice No.

Invoice Date 3/6/25 SERVICE

K. to Pay H. 9062 7-25 K. H. 9062 Equipment # 9062

Invoice To

GENESEE COUNTY SURFACE WATER

4608 BEECHER ROAD **FLINT MI 48532**

Ship To:

GENESEE COUNTY SURFACE WATER

4608 BEECHER RD **FLINT MI 48532**

INFORMATION

Job Number:	86003	Due Date:	04/20/2025	Customer Code.:	GENE0004
Service Date:	2/26/25	Taken By:	ASCHMELING	Site Code:	_MAIN
Branch:	1100	Equip. Hours:	5,798	Site Contact:	
P.O. No.:	9062	Equip. Miles:	37,758	Phone:	
Equip. No:	15441	Make:	VA	Serial No.:	18-05V-17454
Customer Eq. No:	15441	Model:	2100P	Chassis VIN:	1FVHG3FE7KHKA8495

Equip. Desc: 2115SE2P100A - 2115

SE 2-STAGE PLUS

100GPM A

NOTES

Service Job Notes:

CONTACT: RJ 810-691-7657

- PUMP OFF WEAK
- VAC RPM INOP
- RODDER PUMP MAKING NOISE
- WATER PRESSURE WEAK
- HYD PUMP SOUNDED LOW, HYD FLUID LOW

INSPECTED TRUCK, MADE SURE ALL HYDRAULIC VALVES ARE IN OPEN POSITION, TRUCK LOW HYDRAULIC OIL. FOUND THAT TRASH PUMP WAS LEAKING OIL INSIDE BODY FROM PRESSURE LINE THAT IS RUSTED OUT. REMOVED TRASH PUMP, INSTALLED 2 NEW FITTINGS INSIDE TUNNEL WALL, BLOCKED THEM OFF FILLED WATER TANKS, RAN WATER SYSTEM AND VACUUM SYSTEM, ADDED 25 GALLONS OF HYDRAULIC OIL. UNIT RAN FINE. HAD A HARD TIME GETTING KING NIPPLE OUT OF BODY, HAD TO CUT IT OUT, INSTALLED NEW ONE. BUILT NEW TRASH PUMP ASSEMBLY, MOUNT IN BODY, TEST RAN TRASH PUMP, DID NOT SEE ANY LEAKS, FILLED BODY WITH WATER AND RAN PUMP. WORKS AT THIS TIME. INSTALLED NEW 3" BALL VAVLE & CAMLOCK FITTING CAP ON OUTSIDE, PAINTED EXTERNAL PIPE. TIGHTENED UP AND LOCTITE SET SCREWS FOR REAR BEARING LOCK ON HOSE REEL. TOPPED OFF HYDRAULIC OIL, 15 GALLONS. COMMUNICATED WITH RJ AND HE REQUESTED WE PERFORM 500HR SERVICE THAT WAS DUE. CHANGED OIL, AIR, FUEL FILTERS, AND MOTOR OIL. REPLACED CABIN AIR FILTER. DRAINED OIL IN T-CASE, REFILLED OIL IN T-CASE. HAD TO BLEED FUEL SYSTEM TO GET UNIT STARTED AFTER CHANGING FUEL FILTERS. CHECKED TRANS OIL & REAR OILS. GREASED UNIT. REMOVED AIR DRYER, REPALCED CARTRIDGE & REINSTALLED. FILLED TRANS DRIVE FOR HYDRAULIC FAN DRIVE. AIRED UP ALL REAR DRIVE TIRES, ALL WERE LOW. TIGHTENED FILL PLUGS ON T-CASE. TEST RAN UNIT. NEXT SERVICE DUE AT 6298 ENGINE HOURS.

PLEASE SEE OUR TERMS AND CONDITIONS ON OUR WEBSITE TEAMJDC.COM



Remit To: **Jack Doheny Company** PO BOX 675546 DETROIT, MI 48267-5546

INI	OICE	Inv	oice No.	257300	Invoice Date	3/6/25		SERVICE
DET	AILS		0, K. to 3-7-25 Equipm	Pay . H.				
Qty		Part No.	Description		Rate	Price	Tax	Amount
1.00	OTHER	SHOP SUPPLIES	SHOP SUPPLIES		\$529.17	\$529.17	\$0.00	\$529.17
2.00	PART	VA-1099061	CARTRIDGE-HYD FILTER		\$176.32	\$352.64	\$0.00	\$352.64
1.00	PART	HF-2501-8-8	1/2MJ X 1/2MP 90 ELB		\$4.75	\$4.75	\$0.00	\$4.75
40.00	PART	ZO-AW68	HYD OIL (GAL)		\$15.35	\$614.00	\$0.00	\$614.00
1.00	PART	JS-1009	3" TRASH PUMP INSTA		\$3,400.00	\$3,400.00	\$0.00	\$3,400.00
1.00	PART	ZF-500925	FILTER AIR P	634517	\$248.49	\$248.49	\$0.00	\$248.49
1.00	PART	ZF-600564	FUEL FILTER (FF63009)		\$64.32	\$64.32	\$0.00	\$64.32
1.00	PART	ZF-DDE-R61709	FILTER FUEL		\$78.97	\$78.97	\$0.00	\$78.97
1.00	PART	ZF-1748	OIL FILTER (LF3000)		\$71.00	\$71.00	\$0.00	\$71.00
1.00	PART	ZF-9520	AIR FILTER		\$88.99	\$88.99	\$0.00	\$88.99
1.00	PART	ZF-9082	CABIN FILTER		\$26.25	\$26.25	\$0.00	\$26.25
10.00	PART	ZO-75W90	75W90 GEAR OIL (QT)		\$29.91	\$299.10	\$0.00	\$299.10
5.00	PART	ZO-ISO46-GST	COTTA OIL, QUARTS		\$3.58	\$17.90	\$0.00	\$17.90
22.00	PART	ZO-15W40	ENGINE OIL (QUART)		\$4.73	\$104.06	\$0.00	\$104.06
1.00	PART	ZF-107794X	REMANUFACT		\$50.40	\$50.40	\$0.00	\$50.40
29.50	LABOR	STRAUB	GENERAL LAB	R BRAKE DRYER C OR	\$175.00	\$5,162.50	\$0.00	\$5,162.50

 Labor Total:
 \$5,162.50

 Parts Total:
 \$5,420.87

 Consumables:
 \$0.00

 Freight:
 \$0.00

 Other:
 \$529.17

 Tax:
 \$0.00

 Total:
 \$11,112.54

Name:

Signature: ____ Date: ____

Payment Terms: 45 DAYS FROM INVOICE

PLEASE SEE OUR TERMS AND CONDITIONS ON OUR WEBSITE TEAMJDC.COM

248-349-0904
AR@teamidc.com
teamidc.com